

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12078

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080118-3

RECEIVED FROM

G. V. Controls

DATE REC'D. 5-3-57

P.O. NO. 6331

VENDOR PACKING SLIP NO. 6333

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS
									ACCEPTED	REJECTED	
	322	000000	NOTED								
10		730125-13	Relay Time Delay 5 Sec. C-7							10	Must store " 9.
		-04 NC-28 (322-000000-25-C-23)									
10		730125-26	Relay Time Delay 3 sec. (-V OFF)							10	
		-01 NC-28 (322-000000-106-C-23)									
<p>Transperado Rec. Insp. report #13097 dated 5-2-57</p>											

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12089

RECEIVED FROM

2561 E. COLORADO ST., PASADENA CALIF.

PLATE #9

DATE REC'D. 5-6-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS
									ACCEPTED	REJECTED	
4	322	000000	10	0	20					4	<p>IFB #2307</p> <p>Ref: Stores Req: 71630</p> <p>(Take W.A. ONLY EL)</p>

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080118-3

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.